

# TABELA DE MEDIDAS



POLIACETAL POM - P.S.A

## BARRAS



Medida	Peso
6 X 3000	0,14
8 X 3000	0,25
10 X 3000	0,37
13 X 3000	0,60
15 X 3000	0,80
16 X 3000	0,93
20 X 3000	1,43
22 X 3000	1,73
25 X 3000	2,25
28 X 3000	2,75
30 X 3000	3,15
32 X 3000	3,60
35 X 3000	4,42
40 X 3000	5,70
45 X 3000	6,84
50 X 3000	8,82
55 X 3000	11,10
60 X 3000	12,50
65 X 3000	14,90
70 X 3000	17,38
75 X 1000	6,60
80 X 1000	7,50
85 X 1000	8,30
90 X 1000	9,50
100 X 1000	11,80
110 X 1000	14,30
120 X 1000	17,80
130 X 1000	20,00
140 X 1000	23,40
150 X 1000	26,30
160 X 1000	30,20
170 X 1000	34,00
180 X 1000	37,80
200 X 1000	46,80
230 X 1000	63,00
250 X 1000	74,40
300 X 1000	106,50

## CHAPAS



Medida	Peso
6 X 500 X 3000	13,70
6 X 1000 X 2000	18,40*
8 X 500 X 3000	18,40
8 X 1000 X 2000	24,60*
10 X 500 X 3000	23,80
10 X 1000 X 2000	31,00*
12 X 500 X 3000	28,00
12 X 1000 X 2000	37,00*
15 X 500 X 3000	34,50
15 X 1000 X 2000	46,50*
20 X 500 X 3000	46,00
20 X 1000 X 2000	61,00*
25 X 500 X 3000	57,00
25 X 1000 X 2000	76,00*
30 X 500 X 3000	69,00
30 X 1000 X 2000	91,00*
40 X 500 X 3000	91,50
40 X 1000 X 2000	122,00*
50 X 500 X 3000	112,00
50 X 1000 X 2000	150,00*
60 X 500 X 3000	136,00
70 X 500 X 3000	157,00
80 X 500 X 3000	183,00
100 X 500 X 3000	230,00

DIMENSÕES (MM)  
 PESOS (KG/PEÇA) APROXIMADOS  
 (\*) MATERIAL SOB CONSULTA