



BARRAS (Medidas mm)	Peso / pç
12x1000	0,260
14x1000	0,340
15x1000	0,400
16x1000	0,460
18x1000	0,600
20x1000	0,720
25x1000	1,140
30x1000	1,580
35x1000	2,180
40x1000	2,940
45x1000	3,560
50x1000	4,400
60x1000	6,700
65x1000	7,480
70x1000	8,760
75x1000	10,180
80x1000	11,540
90x1000	14,600
100x1000	17,880
110x1000	22,400
120x1000	25,840
130x1000	30,540
150x1000	40,000
160X1000	45,160
180x1000	58,000
200x1000	67,800
230X1000	91,960
250X1000	108,000
300X1000	157,820
CHAPAS	Peso / pç
1x1000x1000	2,340
2x1000x1000	4,500
3x1000x1000	6,760
4x1000x1000	9,014
5x1000x1000	11,340
6x1000x1000	13,900
8x1000x1000	18,300
10x1000x1000	23,600
12x1000x1000	27,600
15X1000X1000	35,000
20X1000X1000	46,600
25X1000X1000	58,300
30x1000x1000	69,400
32x1000x1000	82,300
35x1000x1000	82,950
40x1000x1000	94,100
50X1000X1000	120,200