

TABELA DE PESOS E MEDIDAS



POLIAMIDA 6 G - PA 6 G - P.S.A

BARRAS



Medida	Peso
80 X 1000	6.50
90 X 1000	8.10
100 X 1000	9.89
110 X 1000	11.76
120 X 1000	14.21
130 X 1000	16.84
140 X 1000	19.57
150 X 1000	22.40
160 X 1000	24.50
180 X 1000	32.34
200 X 1000	38.55
230 X 1000	50.85
250 X 1000	60.50
280 X 1000	76.33
300 X 1000	85.60
320 X 1000	98.00
350 X 1000	117.50
400 X 1000	152.50
500 X 1000	246.00

CHAPAS



Medida	Peso
10 x 1000 X 2000	24.61
15 X 1000 X 2000	40.00
20 X 1000 X 2000	52.00
25 X 1000 X 2000	64.00
30 X 1000 X 2000	77.00
40 X 1000 X 2000	102.00
50 X 1000 X 2000	127.00
60 X 1000 X 2000	152.00
70 X 1000 X 2000	175.75
80 X 1000 X 2000	202.00
100 X 1000 X 2000	252.00

DIMENSÕES (MM)
PESOS (KG/PEÇA) APROXIMADOS
(*) MATERIAL SOB CONSULTA
(*) CONSULTE OUTRAS MEDIDAS

